Médiatech
Fournitures d'impression et équipements

MURALTAC-FAB

FICHE TECHNIQUE

High Opacity & Removable Self adhesive Textile

100% polyester woven fabric that has pressure sensitive adhesive enabling to be repositioned instantly and to be removed. With high opacity, it is effective to cover the surface color or pattern of host surface and easily removable with nearly no residue left. No rip (Tear free) and durable. The life time of the adhesion power is subjected to the surface condition so pre-test on the host wall is recommended. Ideal for any board displays, Interior decorations, Wallpaper, window backlits and acrylic board display etc. Compatible with Solvent based ink, HP Latex and UV ink.

Products

Code	Compatible ink	Total weight, Thickness	Thick. of backing paper
MURALTAC-FAB	Solvent based ink and HP Latex, UV	305 gsm, 340 mic	143 mic

Specification

Base material	100% polyester Woven fabric	**Surface finish**	Matt
Backing liner	Double side PE coated paper	**Optimum printer temp.**	70°F (21 °C)
Denier	150 x 150	**Adhesive type**	Solvent based Acrylic
Ink limit	250%	**PVC Free**	Yes
Backing Film (Paper)	Recyclable	**Water resistant**	Yes

Available roll size

For Solvent based ink	42", 50", 54" and 60"

Core size

Diameter of Core	3 inch
Thickness of Core	4 mm

* Roll length: All 30 meters (Customized size is available)

Application

- Wallpaper / Mural
- Indoor / Outdoor Decoration
- Exhibition Graphics
- Point of Sales (POS)
- Label / Photo sticker
- Any Board Displays
- Vehicle Graphics
- Booth Display

Installation Guideline

Surface Preparation
Always ensure that the receiving substrate is thoroughly cleaned, free of dust, dirt or cleaner residues. Metal and glass surfaces can be cleaned with standard glass cleaners. Poor surface conditions will cause adhesion loss or failure. Minimum surface temperature is 50ºF (10ºC). Life expectancies can vary depending on mounting surface and weather conditions.

Installation Techniques
Proper contact of the adhesive to mounting substrate is critical and maximum pressure should be used during installation. If insufficient pressure is used during the install, the edges can lift. It is recommended that a cold roll laminator be used to give adequate, even pressure during application. It is not recommended to use water during the installation.

Finishing:
Let image dry completely before applying a finish.

Removal
When removing from any surface, remove slowly and lift at a 90º angle. Because the material is tear-free (durable) and removable adhesive, it is basically easy to remove from any surfaces. However, different surfaces will have different adhesion characteristics. Glass, stainless steel, and aluminum surfaces usually promote higher adhesive bonds and may leave a bit adhesive residue during removal. If during the removal adhesive transfer happens, soapy warm water and aggressive rubbing with a cloth should easily remove adhesive.